


15. 19. 10.

March 13th 1827 Surveyed Section 10. T19. R15.
in the following manner.

W. Oak 18 N 24 E 32.
do 25 N 78 E 21.
K 318.20 A F
W. Oak 12 N 16 E 26.
do 8 S 29 W 20.
W. Oak 10 S 20 E 30.
B. Oak 20 S 29 W 40.

K	W. Oak	13	N 34 W	28 1/2	Stone 10"
"	Gum	7	S 47 W	30	Stone 10"
F	W. Oak	18	N 5 E	62 1/2	Stone 10"
"	Hickory	13	N 87 W	48	
B	W. Oak	16	S 24 W	45	Stone 12"
"	Dogwood	6	S 69 W	17 1/2	
H	Chicknut	19	S 45 E	44	Stone 9"
"	W. Oak	36	N 62 W	33	
G	B. Oak	20	S 21 W	16	Stone 12"
"	Hickory	11	N 37 E	44	
E	B. Oak	10	N 30 W	13	Stone 9"
"	W. Oak	6	N 85 E	18	
I	B. Oak	4	N 48 E	25	Stone 14"
"	B. Walnut	10	S 39 W	44	
L	W. Oak	40	N 56 W	37	
"	W. Nut	5	S 14 W	17	
M	Dogwood	6	N 4 W	16	
N	W. Oak	16	N 10 W	28.	



Hickory 6 S 70 E 15.
W. Oak 23 N 42 W 41,
W. Oak 21 S 76 E 27.
do 16 N 53 W 36.
B. Oak 10 S 33 E 7.
Dogwood 4 N 53 W 13.

7. 9. 32 10⁺
37 9⁺

Surveyed June 10th 1859.
For Louis Moyers

Now owned, March 6th 1905. by
S. B. Fair and L. M. Miller.
Recorded by H. H. Robinson
County Surveyor.

"D."	1	S 8 W	5.
	2	S 39 E	6.20
	3	S 70 E	7.
	4	S 42 1/2 E	8.
	5	S 28 W	10.
	6	S 35 W	6.12
	7	S 52 W	8.
	8	S 57 W	8.
	9	S 62 1/2 W	8.
	10	S 66 W	4.
	11	S 55 1/2 W	8.
	12	S 53 W	6.
	13	S 42 W	6.
	14	S 24 W	6.
	15	S 43 W	6.
	16	S 55 1/4 W	10.
	17	S 62 W	6.
	18	S 31 E	4. 18
	19	S 78 1/2 E	7.
	20	N 86 E	6.
	21	S 52 E	7.
	22	S 15 1/2 E	8.
	23	S 13 W	8.
	24	S 22 1/2 W	6.
	25	S 20 1/2 E	13. blew into creek
	26	S 13 W	15.
	27	S 71 E	16.
	28	S 49 E	9.
	29	S 8 E	8.
	30	S 35 W	8. cross Killbuck on new cut.
	31	S 47 1/2 W	7.
	32	S 15 W	2.
	33	S 43 E	2.
	34	N 77 E	4.
	35	N 37 E	8. to Killbuck new cut.
	36	N 20 E	6.10
	37	N 37 E	7.
	38	N 79 E	8. to R R
	39	S 41 E	10.
	40	S 14 W	6.10 to corner (original)

